

**Schedule of Accreditation**  
**Motabaqah Vehicles Inspection Laboratory-Batha Branch**  
 Batha port – behind PRO oil gas station, Kingdom of Saudi Arabia.

Schedule No.: 414003 B

Issue No. (1): February 19, 2015

Revision No. 1: April 17, 2016

Valid to : February 18, 2019

Materials / Products Tested	Types of Tests / Properties/Measured / Range of Measurements	Standard Specifications / Techniques Used
<b>Cars</b>		
<b>Exhaust Engine</b>	Measurement of CO & HC	SASO 1284:1998 Gulf 971:1998 item 4/18/1)
<b>Engine</b>	Measurement of Engine operation efficiency	SASO 1284:1998 Gulf 971:1998 item 4/3/4/4
<b>Glass</b>	Glass damage test -measurement of glass damage	SASO 1284:1998 Gulf 971:1998 item 4/13/4/3
	Glass tinting test -measurement of percentage glass tinting	SASO 794:1998 Gulf 684:1997 item 4.13.3
<b>Brake</b>	Brake & suspension tests -brake testing system -suspension testing system	SASO 1284:1998 Gulf 971:1998 Item 4/2/1, Item 4/4/1, Item 4/7, item 4.9
<b>Tire</b>	Tire wear test -measurement of tire wear	SASO 1284:1998 Gulf 971:1998 item : 4/5/1
	Tire damage test -measurement of tire damage	SASO 1284:1998 Gulf 971:1998 item 4/5/3

HANY EDESSOUKI

Schedule of Accreditation

Motabaqah Vehicles Inspection Laboratory-Batha Branch  
 Batha port – behind PRO oil gas station, Kingdom of Saudi Arabia.

Schedule No.: 414003 B

Issue No. (1): February 19, 2015

Revision No. 1: April 17, 2016

Valid to : February 18, 2019

Materials / Products Tested	Types of Tests / Properties Measured / Range of Measurements	Standard Specifications / Techniques Used
<b>Cars</b>		
Steering	Steering lash-travel test	SASO 1284:1998 Gulf 971:1998 item 4/6/1
Light	Light High beam intensity and direction test -measurement of light intensity -measurement of light direction	SASO 1284:1998 Gulf 971:1998 item 4/10/2
Body Paint	Paint test -measurement of coating thickness	SASO 1284:1998 Gulf 971:1998 Item 4/16/4
Battery	Battery efficiency test -measurement of battery efficiency	SASO 1284:1998 Gulf 971:1998 Item 4/11/4
	<b>Visual Inspection</b>	
	Tire & wheel	Visual inspection
	Steering lash – travel	SASO 1284:1998 Gulf 971:1998 Item 4/9/1
	Electrical system	
	Ball joint wear	
	Exterior components & sheet metal	
	Vehicle glazing	
	Sun vision ,seats,safety belts & safty tools	
	Mirror,windsheld wipers & washers	

Hany El Desouki